

Brugervejledning - DK

Produktnavn D-S Blue Skinnex®
Vare nr. 13-780
Str. 10, 11
Produktbeskrivelse: TIG/MIG svejsehandske i spalt med forstærkning i håndfladen og komfortabelt bomuldsfor. Syet med Kevlartråd.

A. Brug

Disse handsker er konstrueret til primært at beskytte hænderne mod mekaniske og/eller termiske risici.
De opfylder kravene i EU-direktivet 89/686/E0F med ændringer og er mærket tilsvarende.
Endvidere opfylder de de gældende europæiske standarder.
Handskerne må kun anvendes til det beregnede formål.
Forklaring til piktogrammer og relevante gældende standarder:

EN 388:2003



4133

EN 407:2004



413X4X

EN420:2003+A1:2009



EN 12477:2002+A1:2005
TYPE A

Kategori II



AZO-fri
Krom testet

EN 12477 A = Beskyttende handsker som bruges til svejse applikationer ved høj varme, inklusiv elektrodesvejsning og MIG-svejsning.

EN 12477 B = Beskyttende handsker som bruges til svejseapplikationer ved lavere temperaturer, som kræver fingerfærdighed, inklusiv TIG-svejsning.

EU-typegodkendelse fra Centexbel Belgium (I.D. 0493), Technologiepark 7, B-90S2 Zwijnaarde.
Yderligere informationer om produktets ydeevne og et eksemplar af konformitetserklæringen kan fås ved henvendelse til D-S Sikkerhedsudstyr A/S.

B. Forholdsregler ved brug

1. DISSE HANDSKER MÅ IKKE ANVENDES SAMMEN MED KEMIKALIER.
2. Handskerne bør ikke anvendes, hvor der er en risiko for at sidde fast i bevægelige maskindele.
3. Undersøg handskerne for fejl og skader før brug. Undgå at anvende beskadigede, snavsede eller slidte handsker.
4. Handskerne må ikke komme i kontakt med åben ild.
5. Handskerne modstår normalt gennemtrængning af UV-stråling. Der findes ingen standardiseret testmetode til konstatering af UV-stråling.
6. Når handskerne anvendes til lysbuesvejsning, bør de ikke anvendes til at beskytte mod elektrisk stød. Den elektriske bestandighed er nedsat, når handskerne bliver våde.

C. Bestanddele / farlige bestanddele

Handskerne kan indeholde bestanddele, som er kendt for at forårsage allergier hos følsomme individer, der kan udvikle irritation og/eller allergiske kontakt reaktioner. Hvis der skulle opstå allergiske reaktioner, skal der straks ske henvendelse til en læge.
Yderligere informationer kan fås ved henvendelse til D-S Sikkerhedsudstyr A/S.

D. Plejeanvisninger

Opbevaring: Må ikke udsættes for direkte sollys. Skal opbevares på et køligt og tørt sted.
Må ikke udsættes for ozonkilder eller åben ild.
Rengøring: Handskerne tåler ikke vask.

E. Bortskaffelse

Bortskaffes i overensstemmelse med de lokale regler. Deponeres eller forbrændes under kontrollerede forhold.

Forpakning:
1 par pr. pose. 30 par pr. karton.

Yderligere information:
D-S Sikkerhedsudstyr A/S
Tlf. +45 55 44 66 44
E-mail: info@d-s.dk
www.d-s.dk



Din Sikkerhed
D-S Sikkerhedsudstyr A/S

User manual - EN

Product name D-S Blue Skinnex®
Product code. 13-780
Size. 10, 11
Product description: TIG / MIG welding glove in split leather with reinforcement in the palm of the hand and comfortable cotton lining. Kevlar stitching.

A. Use

These gloves are designed to protect the hands and/or forearms against mainly mechanical and/or thermal risks. They are in conformity with, and are marked per the requirements, of the European Directive 89/686/EEC and Its amendments. They also comply with the applicable European Standards. Please ensure the gloves are used only for the designated purposes. Explanation of pictogram, and relevant complying standards

EN 388:2003



4133

EN 407:2004



413X4X

EN420:2003+A1:2009



EN 12477:2002+A1:2005
TYPE A

Category II



AZO-free
Chrome tested

EN 12477 A = Protective gloves used in higher-heat welding applications, including Stick and MIG welding.

EN 12477 B = Protective gloves used in lower-heat welding application that require high dexterity, including TIG welding.

EC-Type examination certificate from Centexbel Belgium (1.D. 0493), Technologiepark 7, B-9052 Zwijnaarde.

For more detailed Information on the product's performance and to obtain a copy of the Conformity Declaration, please consult D-S Safety.

B. Precautions for use

1. NEVER USE THESE GLOVES WITH CHEMICALS.
2. The gloves should not be used when there is a risk of entanglement with moving machine parts.
3. Before usage, inspect the gloves for any defects or imperfections. Avoid wearing damaged, dirty or worn out gloves.
4. The gloves should not come in contact with a naked flame.
5. The glove does not normally allow penetration of UV radiation. There is no standardised test method for detecting UV penetration.
6. When gloves are being used for Arc welding, they should not be used to protect against electric shock. The electrical resistance of the glove is reduced if gloves get wet

C. Ingredients / Hazardous Ingredients

Gloves might contain Ingredients which are known to be a possible cause of allergies in sensitised persons, who may develop Irritant and/or allergic contact reactions. If allergic reactions should occur, obtain medical advice immediately.

For more information, please contact Ansell's Technical department.

D. Care Instructions

Storage: Keep away from direct sunlight; store in a cool dry place.

Keep away from ozone sources or naked flame.

Cleaning: Gloves are not designed to be laundered.

E. Disposal

Dispose of according to Local Authority Regulations. Landfill or incinerate under controlled conditions.

Packing:

1 pair per bag. 30 pairs per carton.

Further information::

D-S Safety A/S

Tel. +45 55 44 66 44

E-mail: info@d-s.dk

www.d-svarmex.com

